

ID	Type	Product	Feature	Name
49132	Other	Other	Adept 3.0	ADEPT 3Prod - "Show Curves" curves not showing
49712	Other	Other	Adept 3.0	Change Sales Order BOD logic for Sales Order Company
49679	Other	Other	Adept 3.0	Adept 3.0 - Unable to modify existing customer information
49788	Other	Other	Adept 3.0	ADEPT3.0 Select - Getting Server error while clicking on Login button.
49792	Other	Other	Adept 3.0	ADEPT 3.0 SELECT Email and Download Error
49820	Other	Other	Adept 3.0	Error in SP code on ADEPT 3
49735	Other	Pumps	Adept 3.0	Adept-3.0 and QA-PRINT-Verify Print for DEVA report
48141	Other	DEVA	Capturing Footprint Savings & Installation Cost Savings for SG & FTV in DEVA	Changes to Piping Arrangements Window
48142	Other	DEVA	Capturing Footprint Savings & Installation Cost Savings for SG & FTV in DEVA	Modify Footprint Formulas for SG, FTV and Mounting Base Inclusion/Exclusion
48143	Other	DEVA	Capturing Footprint Savings & Installation Cost Savings for SG & FTV in DEVA	Add Footprint Calculation for Standalone Drive
46801	Other	Other	DCR-2020-012 Comprehensive Extended Warranty	DCR-2020-012-CEW-Error displayed when commissioning check box is checked
46804	Other	Other	DCR-2020-012 Comprehensive Extended Warranty	DCR-2020-012-CEW-Error when none is chosen
46691	Other	Other	DCR-2020-029 Global PSCP Pricing restructure	Manual select-select any pump and choose pump qty >4; PSCP enabled
47502	Other	Other	DCR-2020-045 Updated Standard Startup and Commissioning	Number of devices should be integer number
49647	BOM	Fire	DCR-2022-003 HFHH Fire Pump 12x8x18NF	DCR-2022-003 - IEC Diesel Engine BOM update for Interchart missing models
49804	Selection	Fire	DCR-2022-003 HFHH Fire Pump 12x8x18NF	NFPA Fire Pump-HFHH-12x8x18NF-Diesel models missing in grid
49905	Other	Other	DCR-2022-005 DE Evercool Parts and Kits	DCR-2022-005 -Getting default part number for selected service parts and kits in submittal report.
49753	Selection	Service	DCR-2022-005 DE Evercool Parts and Kits	Configuration Work for DCR-2022-005 DE Evercool Parts and Kits - Standalone
49752	Selection	Service	DCR-2022-009 Booster Parts and Kits	Configuration Work for DCR-2022-009 Booster Parts and Kits- Standalone
49601	Other	Other	DCR-2022-013 Expansion Tank	DCR-2022-013 - Lead Time mismatch for CA and US
49461	DCR	Pumps	DCR-2022-017 Medium Pump	New Engine work for DCR-2022-017 Medium Pump
49619	Selection	Pumps	DCR-2022-017 Medium Pump	4380 DE Medium Pumps in DCR-2022-017 are only for OEMs
49662	Selection	Pumps	DCR-2022-017 Medium Pump	PEI & ER values for medium pumps in DCR-2022-017
49702	Selection	Pumps	DCR-2022-017 Medium Pump	Update of NPSHr Curve for Medium Pumps in DCR-2022-17
49784	Selection	Pumps	DCR-2022-017 Medium Pump	DCR-2022-017 Medium Pump - UAT changes
49828	Selection	Pumps	DCR-2022-017 Medium Pump	VFDUnitConfigIdx returning as "None" from Json for Design Envelope Medium Pumps
49762	Selection	Service	DCR-2022-018 SMART Recommissioning ADEPT enablement DCR	Configuration work for DCR-2022-018 SMART Recommissioning ADEPT enablement
49759	Selection	Pumps	DCR-2022-020 DEPM2 Motor Change	Configuration work for DCR-2022-020 DEPM2 Motor Change
49034	Other	Other	Engine QA Testing Tool	Circulator Outputs
49731	Other	Other	Engine QA Testing Tool	QA Test Tool modification required
49011	Other	Pumps	Engine QA Testing Tool	Circulator Inputs
49709	Selection	Pumps	Obsolescence prototype	Obsolescence prototype - Transition Phase
49720	Selection	Fire	Post Launch - Catch All	Bad Fire Selections in Rank 1 and 2
45183	Other	Other	Post Launch - Catch All	[CPQ] Total Pump Qty ignored on Automatic selection if user was previously on Manual Selection - Conventional Constant Speed
49734	Other	Other	Post Launch - Catch All	US_UK Markets - CS 4300, 4380 - Wrong Curve IDs were shown.
48986	Selection	Pumps	Post Launch - Catch All	Need Compliant Check for Manually selected Pumps
49479	Selection	Pumps	Post Launch - Catch All	DE Corner points to be corrected in NE
49719	Selection	Pumps	Post Launch - Catch All	New E3212 and E3355 files from Engineering
49775	Selection	Pumps	Post Launch - Catch All	Search Results Grid List Price Column Header
49506	Selection	Pumps	Post Launch - Catch All	Incorrect Motor Curve for CS/VS Pump Selections.
49687	Selection	Pumps	Post Launch - Catch All	4380 4x4x8 1.5hp Non-compliant for CVS??
49763	Selection	Pumps	Post Launch - Catch All	IEC 4300 150-250 3600rpm Curve/Selection error
49793	Selection	Pumps	Post Launch - Catch All	4300 16x16x19 1800rpm showing as non-compliant
49797	Selection	Pumps	Post Launch - Catch All	GTA#76197 - Selection VIL4300 20x20x19
49799	Selection	Pumps	Post Launch - Catch All	IEC 4300 200-375 1800rpm CVS curve error
49613	Reports	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC orifice and peak power - JP review
49556	Other	Other	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Curve issues from JP testing
49789	Other	Other	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC orifice k value incorrect in electric selection

ID	Type	Product	Feature	Name
49744	Drawing	Pumps	Pump Submittal Changes	Design Envelope Pump Submittal and Header changes
48157	Selection	Other	Stability/Validation/Speed	Speed Affected by Size of Quote
44781	Selection	Boosters		Incident #44356 LN Item Description Error
49290	Other	DEVA		Update Global Database of Piping Costs
49593	Selection	Fire		Incident #73752 Adding 8 nos. Parts kits in NFPA Fire package configuration.
49672	BOM	Fire		Reg Test 85 - Fire Pumps - Default partnumber
49757	BOM	Fire		Incident #75501 Missing Fire Pak Kits
49756	Drawing	Fire		Fire pumps - Drawings missing
44256	Other	Fire		FIRESYSTEMS - Missing Flow in configuration results and in the Annex
49400	Other	Fire		NFPA DE Fire Systems _ Jockey Jump Controller - Getting error when change Labelling option.
46990	Selection	Fire		Incident #47977 - [replacement bug] The Listed Fire pump and motor is missing the pump listings for VIL
48535	Selection	Fire		Incident #63052 4x3x9 Fire Pump 230/3/60 Error
46684	Selection	iFMS		Incident #50292 RE: iFMS adept UAE not working
47121	Other	iFMS		Packaged Systems Solution iFMS remove value from "System head" field (Production)
49822	Selection	LPC		LPC orifice MFA point above the impeller curve
49645	BOM	OEM		Incident #74399 Daikin Configurator Update - Add Motor Drip Covers
44434	Other	Other		Incident #43326 -REVISED PURCHASE ORDER NR. 1072/20 SQLB000052_3 - DH-ONE Ethiopia Project - Generic codes to be created in co. 67
49058	Other	Other		Incident #63914 RQ for access to quote
49573	Other	Other		Cache Project List from CRM - reference from TP #49545
49608	Other	Other		Incident #73948 Remove performance test operation for 4300 pump routing
49629	Other	Other		Incident #74239 Removal of Product Information data from MEA Submittals
49656	Other	Other		ADEPT 3.0 Placeholder
49657	Other	Other		BaaN Placeholder
49685	Other	Other		Change request to address details
49701	Other	Other		Expedite WF On Expired do not reset delivery time if Quote is Placed
49765	Other	Other		Disable the X (close) button in PriceAdjustment Popup Window
49768	Other	Other		Clean up of GTA tickets assigned to CPQ Configurators
49783	BOM	Other		Reg Test 86 - Pumps Default part number
44668	Other	Other		Reported by Anne-Report error for ETO Packaged systems
46825	Other	Other		A Negative value for "Min.Maintain Pressure" - VS (CPQ)
46925	Other	Other		NCP for 4360 manual select not clearing
47119	Other	Other		Everlasting curve loading - NE & COM
47186	Other	Other		Error when try to request email from schedule for some DE pumps
47359	Other	Other		Replacement listed fire pump and driver selection not able to select VIL
47639	Other	Other		UK Order placing error- Manufacturing company is null from rules for particular product
47790	Other	Other		Get result button disappears & Speed field is disabled - QA
47870	Other	Other		Cannot add ETO packaged system_ QA - ME,US
48720	Other	Other		Incident # 63738 SQO043507-2 - import feature disabled?
48723	Other	Other		Incident #61366 FW: UserTask assigned to you; ARM request for your (NSM) review - Quote: SQXM002716_4
48724	Other	Other		incident #61246 Incorrect DEVA List Price
48857	Other	Other		ARM System Status Changed to open after opening the quote in OBO Account
48859	Other	Other		Incident #65617 Fw: PRIX SOUMISSION - Ecole Pierre Eliot Trudeau
49145	Other	Other		WPD REP DIRECT US - Getting attention required error for pump while validating the Quote.
49304	Other	Other		#44213 Remove 250-315 Pump Model for 4280 and 4030 Pumps from ADEPT selections - IEC Regions
49347	Other	Other		Shipment indicator for Suction guide in LA Market is incorrect
49404	Other	Other		LA Market - Line Drawing is missing for Vortex Air Separator.
49524	Other	Other		Blocked by 49919-validating product catalogue items
49563	Other	Other		incident #73434 Functionality of Close button [x] during a Change option in configuration is not working correctly
49659	Other	Other		Pumps - Select All not working as expected-New Engine Test
49682	Other	Other		Add attachment option is missing in Email pop-up
49684	Other	Other		Adept 3.0 - On click of calendar control and select date, the control wont go away for some time.

ID	Type	Product	Feature	Name
49691	Other	Other		Obsolete DE models does not show transition message when selected manually
49706	Other	Other		Getting DefaultKTRPN for Constant Speed pump - APR Market
49708	Other	Other		Steven Baird reports Firepump pump rpm incorrect
49729	Other	Other		Blocked by#49754 -CS 4700 - Flow not updating in the field and on the curve
49733	Other	Other		Discrepancies in QA Test Tool Results-DE Boosters -Efficiency value differs
49764	Other	Other		LA- Shipment indicator wrong for expansion tanks, DAS and VA
49777	Other	Other		View Order Summary Error contact technical support
49778	Other	Other		OBO Account - Ordered Quote - PO Date and PO Requested Ship Date are setting to blank
49829	Other	Other		Post Go Live - Post to DEVA not working
48957	Selection	Packaged Systems		Incident #66489 Correction to ETO Packaged Systems Configurator on CPQ
47002	Selection	Packaged Systems		Incident #51714 ETO ADEPT Configurator
49412	BOM	Pumps		Incident #71373 6 Pole Standardization in ADEPT (IEC Market)
49606	BOM	Pumps		Incident #73888 Routing and BOM change for pumps with Shaft Grounding Ring (SGR)
46998	DCR	Pumps		Incident #51877 - EAR M00057   CPQ Update
47024	NCP	Pumps		Incident #51935 4030/4280 PN 25 selection to be NCP in ADEPT for IEC
46497	Selection	Pumps		Incident #48995 Adept image previews
49664	Selection	Pumps		Relocate VFD Supplier for Conventional Variable Speed Configurator
49786	Selection	Pumps		Incident #75765 RE: W/O: 100102406 - Indoor Pump
44070	Other	Pumps		Incident #35951 - Pump Performance data - SQT003692_2
44771	Other	Pumps		Incident # 44578
49686	Other	Pumps		Transition Message is not shown for DE-Discontinued Pumps
49736	Other	Pumps		UK Market - DE4302-80-150 Manual Select getting error.
49810	Other	Pumps		Missing Part Number For DE Pump in US under line details
49478	Reports	Pumps		ADEPT 2.0 - Crashing Error 500 on Download button
44064	Selection	Pumps		Regression Testing - LA Market - Circulators
45085	Selection	Pumps		Incident #46410 Adept Issue/SQQ009452-1-21/01/2021 -MA052 Building 52: Package SU03
45168	Selection	Pumps		Wrong Change of Users Market for LA selection
46549	Selection	Pumps		Incident #49702 Error - adept SQVTI000150-3
47378	Selection	Pumps		Incident #54532 FW: SelecciÃ³n bomba 4030-10x8x15-300 hp
47480	Selection	Pumps		Reg Test - Service kit - add to schedule button is enabled incorrectly.
47696	Selection	Pumps		Incident #56385 NON POTABLE?
47986	Selection	Pumps		Incident #58133 S57 pump (flange issue)
48379	Selection	Pumps		Incident #61476 Why am i getting a no potable water seal when I clearly selected 35% PG
49626	Selection	Pumps		Incident #73952 Feature "units" missing from Features and Options
49681	Selection	Pumps		Incident #74385 Grooved FTV Error
49818	Selection	Pumps		VS parallel operation status issue
49827	Selection	Pumps		Engg UAT on DCR-2022-017
49658	Shipment Indicator	Pumps		Incident #74346 RE: Lead Time Question on 20A073311
49746	BOM	Service		Incident #75186 Spare prices missing SQQ0058759-1
49766	BOM	Service		Incident #75530 Colour not captured for Replacement Motor & Casing in Canada/ US market
49811	BOM	Service		Baan:B#75793,B#75975,B#76103,B#75962,B#76524,B#76596
49837	BOM	Service		Baan : B#76747,B#76728, Fire generic selection update in Baan Co-55,B#77085,
43046	Selection	Service		Incident #36981 RE: TP42151 : Incident #32034 Pump Manager Selection
49815	Selection	Service		Incident #76599 Require routing and data to be captured for Replacement Impellers when selecting by PN method
47067	Qty	Service		Incident #51976 Pump Manager Qty SQQ036869-1
49805	Selection	SG		Incident #66531 EPG configurator not working
47259	Selection	SG		Incident #53642 ADEPT Quote - No Suction Guide selection option
49379	Selection	Shell and Tube		Incident #70882 RE: Shell & Tube HX - selection question
49787	Shipment Indicator	VFD		Incident #75638 VFD lead time update
47481	Selection	VFD		Reg Test - VFD Standalone - alternation option resets